Looking south across Ovingham bridge

Typical condition of cross girders. Note extensive corrosion to top right of photograph

Looking north across Ovingham bridge, showing typical morning congestion

Looking north across Ovingham bridge, showing typical morning congestion