Flood Investigation Report



4.2.2

Location: Alnwick (south)					Incident Date: 28/06/12					
Source(s) of flooding:										
Ordinary	Main	Surface				Tidal				
Watercourse	River	Water	Groundwater	Sewer	Sea	Lock				
		\boxtimes								
		<u></u>								
Impacts	Residential	Business	Other Buildings	Roads	Critical Infrastructure					
(number)	6	0	1	5		0				
Reservoir 156m (covered) FOR REFERE	Swanshi Sunnybank Cottage Torr Swanshi Cottage Forr Swanshi Cottage Golf C Camphill Column Stoneyhilf ENCE PURPOSES ONLY BE REPRODUCED	Swansfield House The Duntern House Id Park ourse) Reservoir (covered)	Meadow Rigg School School Path Giovery Green Faik Title:	Aug Football Form Ground Green Field Industrial Rugby Ground Sorons Grou	St James Estate	P Sta awmili dustrial substrial PW Willowtree Industrial				
Northumberland (County Council	FCERM oduced from Ordnance Survey material with the permiss	Alnwick (south) - areas affer by flooding 28/06/2012 Dm: Date: Scale:	Dwe	llings_areas	Surface water flow direction				
County Hall Morpeth Northumberland NE61 2EF Tel: 01	Ordnance Survey Crown Capyright	oduced from Ordsance Survey material with the permiss y on behalf of the Controller of Her Majesty's Stationary : Unauthorised reproduction infringes Crown Copyright a ecution or civil proceedings. License no. 100049048 (20	Office and 06/12/2013 06/12/2013		ds_affected naryWatercourses					
Other_Buildings										
Description										

Following intense heavy rain on 28th June 2012 major surface water flooding of properties and the road network occurred in the southern area of Alnwick.

Flooding to six properties and a school on Blakelaw Road is known to have occurred, with strong potential of additional affected properties as yet unreported.

Roads worst affected were Hopehouse Lane, Blakelaw Road, Meadow Riggs, Greensfield Avenue and Weavers Way. Extensive damage was incurred to road surfaces and some footways, requiring the Highways team to carry out resurfacing and repair work.

The source of the flooding was surface water that overwhelmed the drainage system. It has been suggested that surface water runoff was contributed from a new housing development site directly to the west of the southern end Blakelaw Road, where major earthworks were taking place.

There are no other known available historic records of flooding in this part of Alnwick.

RMA Actions:					
NCC	Exercised: Proposed:	Repairs carried out by Highways Awaiting further details on flooding to property			
EA	Exercised: Proposed:	Awaiting further details on nooding to property			
NWL	Exercised: Proposed:				
Other	Exercised: Proposed:				
Sign Off Drafted by: Hermes Carlyon Approved by:			Date 08/02/13		
RMA Notification: EA NWL Other (please specify)					