Flood Investigation Report



4.19

Location: Rothbury Incident Date: 25/09/1						9/12
Source(s) of	flooding:					
Ordinary	Main	Surface				Tidal
Watercourse	River	Water	Groundwater	Sewer	Sea	Lock
	\boxtimes	\boxtimes				
Impacts	Residential	Business	Other Buildings	Roads	Critical Infras	tructure
(number)	4	0	0	1	0	
River Gauge Raised Defen Main Rivers	A Properties flooded from surface water at the Maltings. Drain covers surcharged and residents reported a very quick surge of water. Surface water flooding was experienced within the court yard area. Hospital Liby Part Double Cost Reserved MAMPPers Nac ResprictOctob or CAPITAL Costson Cost Vinn the previous for Part Costson Cost Vinn the previous for Part Costson Cost Vinn the Previous Cost Vinn the Part Vinn the P	Back The Riverside fooding Publisher FB Car Pa	Soh Pol-Ho Park area saw extensive to toilets were inundated valer. Flood waters to foot bridge within the South	waler, how overlooping commer can be seen as a commer	per the denountable look of control field with the control field wit	14. Tal. 14. 18. 18. 18. 18. 18. 18. 18. 18. 18. 18

Description

The River Coquet flows through Rothbury, rising in the Cheviot Hills it follows a generally east direction for approximately 64km before discharging into the North Sea at Amble. It has a catchment area of 595km² and an average slope of 108m/km with relatively low permeability cement stone and sandstone underlying the catchment.

A flood alert for low lying areas in upper River Coquet was issued by the Environment Agency at 1800 on 24 September. The rainfall was not sufficient for a flood warning to be issued for this part of the river Coquet.

Residents at Armstrong Cottages confirmed that the demountable flood barrier held. Water came close to overtopping the defence and there were reports of some seepage. There was surface water flooding on the road from Whitton View. The overflow from the defence added to the highway flooding resulting in the wall surrounding Armstrong Cottages to overtop and flood the gardens of the cottages. No properties were flooded at Armstrong Cottage, due to the defences mentioned earlier and the property level protection on the garden wall.

The rear of Riverside Pine Trees House flooded from the River Coquet, in addition the sewerage drain at River Close surcharged, however the property was not flooded. The wrack mark in the Forestry Commission car park was to the very back of the gravelled area. In the Riverside Park area the public toilets were flooded to approximately 7-8ft, flood waters overtopped the foot bridge in the park. The force of water knocked the wall down downstream of the Maltings into the allotments.

At the Maltings 4 properties flooded from surface water at approximately 9:30/10:00am on 25 September 2012. The drain covers surcharged and residents reported a very quick intense surge of

water. Surface water filled the court yard area to a depth of 50cm. RMA Actions: Exercised: Carried out FIR NCC Liaise with all RMAs to investigate mitigating SW flooding in The Proposed: Maltings area of Rothbury Issued Flood Warnings for River Coquet; Exercised: EΑ Assisted with FIR Proposed: Exercised: **NWL** Proposed: Exercised: Other Proposed:

Additional supporting information



Flooding at Rothbury Playground.



Floodgate at Rothbury.

Sign Off			Date	
Drafted by: James Hitching				
Approved by: Aaron McNeill				
RMA Notification: EA	NWL 🏻	Other (please specify)		