

		Road No.	Location	Scheme	Comments	Delivery Area
		C255	C255 Ovingham Bridge - Scour to Piers	Major Works	Opened to traffic on 5th September 2016, minor reinstatement works required in spring.	Central
		C146	C146 High House Road, Morpeth	Road Repair	Complete	Central
		C356	C356 Berwick Hill Road	Road Repair	Complete	Central
		C343	C343 Stamfordham Road/Throckley Fell	Road Repair	Complete	Central
		C137	C137 Burgham Road	Road Repair	Complete	Central
		C149	C149 Mitford Church	Design ONLY	Study complete, now subject to routine monthly monitoring.	Central
			Surface Dressing	Surface Dressing	Complete	Countywide
		C168	C168 Pauperhaugh	Major Works	Complete	North
		Reedsford Bridge FP7	Reedsford Bridge FP7	RoW repairs	Complete.	North
		B1340	B1340 Links Road/Front Street, Bamburgh	Road Repair	Complete	North
		U113	U113 Prior Road, Berwick (microasphalt)	Road Repair	Complete	North
		C57	C57 East Ord Village (microasphalt)	Road Repair	Complete	North
		B1340	B1340 St. Aidens, Seahouses	Road Repair	Complete	North
		A1068	A1068 Amble to Hipsburn (various)	Road Repair	Complete	North
		B1339	B1339 Newton to Lesbury (various)	Road Repair	Ongoing - additional works near Embleton Mill	North
		C90	C90 Lemmington Bank	Road Repair	Complete	North
		C172	C172 Whittingham to Netherton (Eslington Hall)	Road Repair	Complete	North
		U3053	U3053 Rugley Road, Alnwick	Drainage	Work complete	North

		Road No.	Location	Scheme	Comments	Delivery Area
		U4015	U4015 Scrainswood	Road Repair	Complete	North
		B1340	B1340 Brunton	Design ONLY	Study complete, the erosion is historical and little has changed over the past 5 years, road is in no danger at present therefore determined that no works required at the current time.	North
		Blyth BR108	Blyth BR108	RoW repairs	Complete.	South East
		U6705	U6705 Remshied Way Roundabout, Ashington	Road Repair	Complete	South East
		C399	C399 Woodhorn Road, Ashington	Road Repair	Complete	South East
		U6555	U6555 Dale Street, North Blyth	Road Repair	Complete	South East
		U6538	U6538 Grange Avenue, Bedlington Station	Road Repair	Complete	South East
		U9564	U9564 Sandford Avenue/Silverdale, Cramlington	Road Repair	Complete	South East
		U9558	U9558 Horton Drive, Cramlington	Road Repair	Complete	South East
		C110	C110 Lynemouth to Cresswell	Road Repair	Complete	South East
		B1322	B1322 Backworth Lane	Road Repair	Complete	South East
		U9508	U9508 Ravensdale Grove, Blyth	Road Repair	Complete	South East
		U9506	U9506 Chasedale Crescent, Blyth	Road Repair	Complete	South East
		C253	C253 Bywell Landslip	Major Works	The road was re-opened to traffic on Friday 21st October 2016. Riverbank restoration works to be carried out during summer 2017	West
		B6529	B6529 Station Road, Corbridge	Major Works	Works ongoing, started on the 9th of Jan 2017, 25 week programme.	West
		A695	A695 Widehaugh Landslip	Major Works	Roadworks complete, there are some hedge and tree planting to be carried out in the spring.	West

		Road No.	Location	Scheme	Comments	Delivery Area
		C322	C322 Whitfield	Major Works	Complete	West
		B6319	B6319 Haydon Bridge Embankment	Major Works	Complete	West
		U8037	U8037 Ninebanks	Major Works	The permanent road diversion work was completed on the 3rd February. Rock armour protection of the failed slope will be carried out during the summer 2017.	West
		B6320	B6320 Bellingham to Wark	Major Works	Complete	West
		U8010	U8010 Black Way	Major Works	Complete	West
		C291	C291 Hawksteel	Major Works	Works ongoing	West
		U8148	U8148 Simonburn incl MARP scheme	Structures	Complete	West
		South Tyne Trail	South Tyne Trail	RoW repairs	Complete	West
		B6306	B6306 Linnels	Road Repair	Complete	West
		B6307	B6307 Linnels	Road Repair	Complete	West
		B6321	B6321 Corbridge	Road Repair	Complete	West
		A68	A68 Healy Snods Edge	Road Repair	Complete	West
		C270	C270 Slaley	Road Repair	Complete	West
		A695	A695 Farnley	Road Repair	Complete	West
		U5039	U5039 Boat Road, Bellingham	Drainage	Complete	West
		U5023	U5023 Woodhouse to Little Ridsdale	Drainage	Complete	West
		U5049	U5049 Ridley Shield Road	Drainage	Complete	West
		U5047	U5047 Sundaysight Road	Drainage	Complete	West
		U8161	U8161 Keepwick Fell	Drainage	Complete	West
		U5042	U5042 Various locations	Drainage	Complete	West
		U5043	U5043 Rushend to Thorneyburn Church	Drainage	Complete	West

		Road No.	Location	Scheme	Comments	Delivery Area
		U8177	U8177 Acomb to Oakwood	Drainage	Complete	West
		U8156	U8156 Coal Road, Gunnerton	Drainage	Complete	West
		C216	C216 Burnmouth to Chipchase	Road Repair	Complete	West
		U5034	U5034 Blindburn Road	Drainage	Complete	West
		U5035	U5035 Low Carry House, Wark	Drainage	Complete	West
		B6320	B6320 to A68 various locations	Drainage	Works ongoing	West
		B6322	B6322 Haydon Bridge	Road Repair	Complete	West
		C202	C202 Bellingham	Road Repair	Complete	West