Flood Investigation Report



OrdinaryWatercoursesmain_rivers_10k

4.3

Location: Alwinton			Incide	nt Date:	28/06/12, 07/08/12, 25/09/12
Source(s) of flooding Ordinary Ma					Tidal
Watercourse Riv	er Water	Groundwater	Sewer	Sea	Lock
Impacts Reside	ential Business	Other Buildings	Roads	Critical In	frastructure
(number) 5	2	0	2	0	
FOR REFERENCE PURPOSI NOT TO BE REPRODUCE Northumberland County Council	Alwinto Farm		EON Bus	sinesses_areas ellings areas	N Surface water flow direction

Alwinton is situated 16km west of Rothbury on the edge of Northumberland Nation	nal Park.					
Heavy rainfall on 28 June, 7 August and 25 September 2012 resulted in the flooding to properties. In addition to the Rose and Thistle public house and Alwinton Farm, five residential properties were flooded.						
The source of the floodwater was the Hosedon Burn. The Burn overtopped adjacent land and flooding nearby properties.	spilling into					
Work to improve the public sewer system was carried out by Northumbrian W years ago, and residents state that this has alleviated drainage issues to some e						
In September 2008 flooding occurred in Alwinton, affecting the same properties in the plan above.	as identified					
RMA Actions:						
NCC Exercised: Communicated with Parish Clerk to ascertain issues. Undertaken Flood Investigation Report						
Proposed:						
EA Exercised: Proposed:						
NWL Exercised: Proposed:						
Other Exercised: Proposed:						
Additional supporting information						
•						
Sign Off	Date					
Drafted by: Hermes Carlyon	Date					
Approved by: Aaron McNeill						
11 1	15/11/12					

NWL Other (please specify)

RMA Notification: EA