
## **Flood Investigation Report**



## 4.6



## Description

Chathill is located approximately 14km north of Alnwick.

High-intensity rainfall on 28 June 1012 resulted in flooding to the highway and properties to the west of the railway line. Surface water from the highway and land to the south and east of the village was conveyed through the village. Due to the flashy nature of the event the drainage system was overwhelmed. Four properties are reported to have experienced internal flooding, with access problems and 'near misses' reported to at least a further two properties.

There is a longstanding issue of surface water flooding with anecdotal evidence to suggest flooding on four occasions in the last 12 years.

RMA Actions:					
	Exercised:	Flood Investigation carried out			
NCC	Proposed:	Investigate opportunities for funding to support further study and alleviation of the issues.			
EA	Exercised:				
	Proposed:				
NWL	Exercised:				
	Proposed:				
Other	Exercised:				
	Proposed:				
Additional supporting information					





Photos of flooding in Chathill on 28 June 2012

Sign Off			Date	
Drafted by: Hermes Carlyon				
Approved by: Aaron McNeill				
RMA Notification: EA		Other (please specify)		